



Service data bulletin

Instrument: GDS101

Date: 23.03.2006

Created by: Geir Theodorsen

SUBJECT: Fuse FS102 on terminal board blowing. (3,15A slow blow)

SYMPTOM: Instrument "dead"

CAUSE: Short circuit 48V on terminal board in IC404 or IC405.

WHAT TO DO: Unsolder IC404 and IC405. If fuse is not blowing then change both IC404 and IC405
TheTh

IC 404 and IC405

Fuse blowing

