



## Service data bulletin

Instrument: GDS101

Date: 23.03.2006

Created by: Geir Theodorsen

**SUBJECT:** Encoder cable (from I/O board to mother board) can be inserted into wrong position.  
(See picture)  
On newer GDS units the lower pins on encoder cable are blocked.  
This is not implemented on older models, thus there is a possibility to insert it wrong

**SYMPTOM:** Only access to page 1,2 and 3 (after service)

**WHAT TO DO:** On picture the lower pin row is blocked. The upper row is inserted.

