SKIPPER

Service data bulletin

Instrument: GDS101
SDBGDS101_34 Change logic on PI-G032

Date: 20.11.2012
Created by: Sigurd H. Paulsen

Changing the logic on PI-G032

Problem: Change logic to eg. special software.

Fault description: Changing the logic.

How to fix: Power off the GDS101.
                          Remove the old logic seen on below picture.
                          Replace the logic with new logic.