

DET NORSKE VERITAS PRODUCT CERTIFICATE

Certificate No N14018XO

for Valve

	chaser
Vendor:	Skipper Electronics AS
Vendor reference:	
Purchaser:	
Purchaser reference:	
Particulars of Product The product is intended for	
Yard:	- -
Yard No.:	- -
Name of Vessel:	" <u>"</u> "
DNV Id. No.:	
THIS IS TO CERTIFY:	
that the product:	Gate Valve
Type designation:	SB-60-LA
Intended Purpose:	The gate valve may be used in conjunction with installation of speed log or echo sounder
Intended Purpose: Serial/Tag no:	
·	speed log or echo sounder 14236 requirements in:
Serial/Tag no: Has been found to comply with relevant DNV Rules for Classification: Ships a	speed log or echo sounder 14236 requirements in: and HSLC sed: N14018XO on: Valve housing
Serial/Tag no: Has been found to comply with relevant DNV Rules for Classification: Ships a The product / material has been mark	speed log or echo sounder 14236 requirements in: and HSLC sed: N14018XO on: Valve housing

If any person suffers loss or damage which is proved to have been caused by any negligent act or omission of Det Norske Veritas, then Det Norske Veritas shall pay compensation to such person for his proved direct loss or damage. However, the compensation shall not exceed an amount equal to ten times the fee charged for the service in question, provided that the maximum compensation shall never exceed USD 2 million. In this provision "Det Norske Veritas" shall mean the Foundation Det Norske Veritas as well as all its subsidiaries, directors, officers, employees, agents and any other acting on behalf of Det Norske Veritas.

Certificate No N14018XO

Linked Type approvals: S-8070	
Surveyor Supplementary information: The valve housing has been subjected to a hydro-static pressure test, and the valve assembly to a seat leakage test to 5 bar. Holding time 5 minutes.	
Manufacturing Survey Arrangement No: R-2164	
Quality System Certificate No: TI151 ISO 9001:2008	

DET NORSKE VERITAS AS, Veritasveien 1, NO-1322 Høvik, Norway, Tel.: +47 67 57 99 00, Org.No. NO 945 748 931 MVA. Form No.: 71.03a Issue: 2013-11

www.dnv.com Page 2 of 2