



## Service data bulletin

Instrument: GDS101

Date: 23.03.2006

Created by: Geir Theodorsen

**SUBJECT:** Back light on Colour screen may be changed separately.

**WHAT TO DO:** If there is no light on the screen this may be caused by a defect back light. This back light is inside the 10,4" TFT Screen (See picture)  
The back light can not be removed/inserted without lifting the Screen from front plate.  
Too access this backlight remove CPU board, mother board and CPU plate.  
Loose the Screen screws to lift up the screen while removing the back light.

Part needed:

Part no: ZAA-01001BL Backlight for 10,4" Screen

