



## Service data bulletin

Instrument: GDS101

Date: 21.01.2014

Created by: Geir Theodorsen

---

SUBJECT: Printers for connection to GDS 101

WHAT TO DO: All printers must have parallel port ( Centronic plug )

Skipper can supply Epson LQ350 (January 2014)

Required software version:5.04.04 or higher.

Set "printer EPSON-300" in "Screen 9".

Following obsolete printers may be installed:

Epson D88. Requires Software Ware V.5.04.13 or higher

Epson LQ 300+II. Continuous paper. Requires software ver 5.04.00 or higher.

Please note that GDS101 with software version between 5.05.02 and 5.05.08 have to be upgraded to work correct with printers.

These units may be upgraded by downloading the latest software and software procedure from SKIPPER Electronics web page:

[http://www.skipper.no/downloads/cat\\_view/90-software.html](http://www.skipper.no/downloads/cat_view/90-software.html)

Following printers have been connected to GDS 101 with good results:

HP Deskjet 610C, HP 640C, HP Deskjet 690C

HP Deskjet 840C, HP Deskjet 850C, HP Deskjet 890C

HP 920C, HP 930, HP Deskjet 970 CXI.

HP 3820, HP 5550, HP 5652

Olivetti Job-Jet P200 inkprinter

Following Printers does not work :

HP 9300

Epson D88+