

Work Order:5456359-AFirst Visit Date:13-Sep-2022Last Visit Date:19-Sep-2022Vendor PO122264 / 118063Number:OsloSurveyOsloLocation:Oslo

Basic Identification Data

Serial Number Model Number Owner Tag Number Supplier Ref. Number

NOTE: This Report evidences that the survey reported herein was carried out in compliance with one or more of the Rules, guides, standards or other criteria of the American Bureau of Shipping and is issued solely for the use of the Bureau, its committees, its clients or other authorized entities. This Report is a representation only that the vessel, structure, item of material equipment, machinery or any other item covered by this Report has been examined for compliance with, or has met one or more of the Rules, guides, standards or other criteria of American Bureau of Shipping. The validity, applicability and interpretation of this Report is governed by the Rules and standards of American Bureau of Shipping who shall remain the sole judge thereof. Nothing contained in this Report or in any notation made in contemplation of this Report shall be deemed to relieve any designer, builder, owner, manufacturer, seller, supplier, repairer, operator or other entity of any warranty express or implied.



22348 SB-100-SA

Report Details

ABS Stamping	Maltese Cross
5456359	Yes

Design Details

Design state	Drawing Number	Reviewing Organization	Rule Set Name	Rule Set Version
Product Design	17-LD1648327-	London Engineering	Rules for Building and Classing Marine	2022
Assessed	PDA	Department	Vessels	

_

Additional Data

Valve Material Copper

Valve Size 100 mm

Statement of Work - Classification Service - Certification -

- All parts of the machinery/equipment satisfactorily complied with the approved drawings. Amendments, if any, verified to be rectified and considered satisfactory.
- Asbestos-free declaration verified and supporting documentation reviewed.
- The principal data has been verified in accordance with the applicable Rules/specifications and applicable approved plans, and confirmed to be within acceptable tolerances.
- All testing (pressure/load/operational/etc.) has been carried out as applicable and verified in accordance with the applicable Rules/ specifications.
- Testing machines are maintained in a satisfactory condition and records of their recheck or calibration dates confirmed.
- Traceability of materials used on this project has been verified.

Report Findings Statement/Observation

Finding No	Asset	Survey Task	Date Created
202.0	-	Certification <i>-</i> Shell Valve Diam. 100 mm, Shell Valve Diam. 100 mm, Shell Valve Diam. 100 mm	19-Sep-2022

Found

Three (3) DN 100 Side shell valves including intermediate element intended for Echo Sounder Transducer Installation

Hydrostatic pressure test was carried out at 5 bar with closed valve for 5 minutes in accordance with 2022 ABS Marine Vessel Rules 4.6.2/7.3.2.

No leakage or plastic deformation were noted during testing.

Material certificates of valves, intermediate elements and bottom flanges were provided by the manufacturer and satisfactorily reviewed.



Work Order:5456359-AFirst Visit Date:13-Sep-2022Last Visit Date:19-Sep-2022Vendor PO
Number:122264 / 118063Survey
Location:Oslo

The valves were found covered by ABS Product Design Assessment no. 17-LD1648327-PDA.

Closing Paragraph:

The component/equipment was surveyed in accordance with the Rules, specifications, and approved drawings, as applicable, and is eligible for installation on board an ABS classed vessel subject to satisfactory installation and testing, as necessary.

Attending Surveyor(s):

Fuglei, Tor Brodde Signed-off Date: 19-Sep-2022

Reviewing Surveyor(s)

Work Order Reviewer: Vocke, Sebastian Work Order Credit Date: 19-Sep-2022