

## MISCELLANEOUS SURVEY REPORT

Page 1 of 2

SUR	VEY OF:	TRANSBUST	TANKO ETNOT			
			TANKS ETNST			
	rt No.: 803459	Date: 23-FEB-2007	Port: Oslo, Norway			
Vess	el's Name:		Class No./VID/CID:	r		
	Ifacturer:	RONICS AS, NORWAY	Mfg.No.:			
	Purchaser/Builder/S.Y.: FOR STOCK		Hull No.:			
Locat	ation:		Rating (WP): -			
Seria N/A	I Number:		Weight: N/A	Test Pressure: N/A		
	rial Test Report No IEWED AND F	D.: FOUND SATISFACTORY	Service Use: BOTTOM FITTING FOR			
Draw "170	ing No. 18'' /	ABS CERTIFICATE No.: 05 LD501406-P	Date Approved:	ABS Markings AชB OS#		
THIS	IS TO CERTIFY	Y that the undersigned Surveyor to this Burea	u attended for the above survey	and reports as follows:		
TEN	(10) TRANSDU	CER TANKS ETNST:				
The	tanks were exa ign Assessmer	amined in finished condition and found to	be according above drawing	and the ABS Certificate of		
- I - Frank Constant	-	cepted subject to installation on board an	d testing to the satisfaction of	f the attending ABS Surveyor.		
P						
[.]						
	Jef-	OSLO		enstellen 466 Cites (j. Seconder,		
ø	Asbjørn Hilland	, Surveyor, American Bureau of Shipping	Surveyor, American Bureau of Shipping			
		(If additional space is required				
NOTE:	committees, its clien Report has met one and conditions of cla interpretation of this	ses compliance with one or more of the Rules, guides, standards or ts or other authorized entities. This Report is a representation only or more of the Rules, guides, standards or other criteria of America assification and to review the survey records for a fuller description Report is governed by the Rules and standards of American Bure- intemplation of this Report shall be deemed to relieve any design-	that the vessel, structure, item of material, equi in Bureau of Shipping as of the date of issue. F n of any restrictions or limitations on the vessel au of Shipping who shall remain the sole judge	ipment, machinery or any other item covered by this arties are advised to review the Rules for the scope i's service or surveys. The validity, applicability and thereof. Nothing contained in this Report or in any		
nana nanaa						

Report No. OS 803459

Date	: 23-FEB-2007	Page	2	of 2				
Det	ails of Survey (continued)							
		82						
	"Empty"							
	*							
	Asbjørn Hilland, Surveyor, American Bureau of Shipping Surveyor, American Bureau o	f Shipping						
<u></u>			10	N/A				
1.	Manufacture or finishing carried out according to:							
	a) approved plans and to the Rules	$\boxtimes$						
	b) <u>Manufacturer's</u> specifications.							
n	Testing carried out as required by Rules/Specifications and as reported herein							
2.								
3.	Welding plans, procedures & welder qualifications have been reviewed as required by Rule/Specifications and as reported herein	$\boxtimes$						
4.	Nondestructive Examination was carried out as required by Rules/Specifications and as reported herein	$\boxtimes$						
5.	Calibration of testing/measuring equipment confirmed, with records maintained at facility or							
J.	located at works	$\boxtimes$						
_		_	_	_				
6.	Components stamped with report number and ABS markings							
AB 113 Distribution								
Pu	rchaser 2 ·							
AB	S Office @ Destination 1							
AP	ABS Houston CDC 1							
Lo								
Ot	ner							
	A							
Rev	EWED By: February. 2007 C	SIO, NORWA Port	ay					
AB 1				<del>40</del>				