

Work Order: First Visit Date: Last Visit Date:

26-Aug-2024 26-Aug-2024

6572776-A

Vendor Purchase Order Number: 127108/132725

Survey Location:

Oslo

Equipment Certification Report

Asset Type Ship Side Valve

Customer Name JOTRON SKIPPER AS

Customer WCN 500646 Location Oslo

'This is to certify that the undersigned Surveyors to this Bureau did at the request of JOTRON SKIPPER AS, on 26 August 2024 carry out the following survey and report as follows:

Client Asset Name

Quantity

Single Bottom 100mm Ball Valve 8

Name Plate Data

ABS Label Manufacturer Purchaser Designer Spare

Single Bottom 100mm Ball Valve Visvana - Visvana Yes

Basic Identification Data

Serial Number Supplier Reference Number

24454, 24455, 24456, 24457, 24458, 24459, 24460, 24461 SB-100-SB -

Report Details

ABS Stamping Maltese Cross

6572776 Yes

Design Details

Design State Drawing Number Reviewing Organization

Product Design Assessed 22-2329626-PDA London Engineering Department

Additional Data

Design Pressure 2 bar

Valve Material Austenitic Cast Stainless Steel

Valve Size 100 mm

Statement of Work - Classification Service - Certification -

- Company has provided a declaration of conformity as required by International Maritime Organization (IMO) Resolution MSC.282(86), adopting SOLAS Reg. II-1/3-5.2, and the IMO MODU Code 2009, the aforementioned product or design does not contain any form of asbestos.
- Dimensions and tolerances were verified as required by the design approval.
- Material test reports (MTR) were reviewed and found to be the satisfaction of the attending Surveyor. Where required by the Rules, ABS
 material certification reports have been verified.
- Plan review and/or Product Design Assessment (PDA) has identified design restrictions and/or limitations which are to be referenced upon installation onboard the vessel.
- Rule required testing (pressure/load/operational/proof-load/etc.) of the equipment/component was witnessed to the satisfaction of the attending Surveyor.

NOTE: This Report evidences that the survey reported herein was carried out in compliance with one or more of the Rules, guides, standards or other criteria of the American Bureau of Shipping and is issued solely for the use of the Bureau, its committees, its clients or other authorized entities. This Report is a representation only that the vessel, structure, item of material equipment, machinery or any other item covered by this Report has been examined for compliance with, or has met one or more of the Rules, guides, standards or other criteria of American Bureau of Shipping. The validity, applicability and interpretation of this Report is governed by the Rules and standards of American Bureau of Shipping who shall remain the sole judge thereof. Nothing contained in this Report or in any notation made in contemplation of this Report shall be deemed to relieve any designer, builder, owner, manufacturer, seller, supplier, repairer, operator or other entity of any warranty express or implied.



Work Order:
First Visit Date:
Last Visit Date:
Vendor Purchase

26-Aug-2024 26-Aug-2024

6572776-A

Order Number:

127108/132725

Survey Location: Oslo

- Subject to satisfactory installation, testing and trials after installation onboard the vessel.
- · Testing machines are maintained in a satisfactory condition and records of their recheck or calibration dates confirmed.

Statement/Observation

Set of Eight (8) Valves intended for for Echo Sounder Transducer, Doppler Log Sensor, or Speed Log Sensor installation.

Valves assembly may include Intermediate Element, Bottom Flange, Blanking Plate, Intermediate tube, Intermediate Flange.

Hydrostatic pressure test was carried out at 5 bar with closed valve for 5 minutes in accordance with 2024 ABS Marine Vessel Rules 4.6.2/7.3.2.

No leakage or plastic deformation were noted during testing.

Material certificates of valves, intermediate elements and bottom flanges were provided by the Manufacturer and satisfactorily reviewed.

The valves were found covered by ABS Product Design Assessment no. 22-2329626-PDA.

Closing Paragraph:

The component/equipment was surveyed in accordance with the Rules, specifications, and approved drawings, as applicable, and is eligible for installation on board an ABS classed vessel subject to satisfactory installation and testing, as necessary.

Attending Surveyor(s):

Fuglei, Tor Brodde

Signed-off Date: 27-Aug-2024

Reviewing Surveyor(s)

Work Order Reviewer: Vocke, Sebastian Work Order Credit Date: 27-Aug-2024



Work Order:
First Visit Date:
Last Visit Date:

26-Aug-2024 26-Aug-2024

6572776-B

Vendor Purchase Order Number: 127108/132725

Survey Location:

Oslo

Equipment Certification Report

Asset Type Ship Side Valve

Customer Name JOTRON SKIPPER AS

Customer WCN 500646 Location Oslo

'This is to certify that the undersigned Surveyors to this Bureau did at the request of JOTRON SKIPPER AS, on 26 August 2024 carry out the following survey and report as follows:

Client Asset Name

Quantity

Single Bottom 60mm Ball Valve 2

Name Plate Data

ABS Label Manufacturer Purchaser Designer Spare
Single Bottom 60mm Ball Valve MESON AB - MESON AB Yes

Basic Identification Data

Serial Number Model Number Supplier Reference Number

24452, 24453 SB-60-SA -

Assembly Details

Serial Number Model Number

24452, 24453 SB-60-SA

Report Details

ABS Stamping Maltese Cross

6572776 Yes

Design Details

Design State Drawing Number Reviewing Organization

Product Design Assessed 22-2329626-PDA London Engineering Department

Additional Data

Design Pressure 5 bar

Valve Material Austenitic Cast Stainless Steel

Valve Size 60 mm

Statement of Work - Classification Service - Certification -

- Company has provided a declaration of conformity as required by International Maritime Organization (IMO) Resolution MSC.282(86), adopting SOLAS Reg. II-1/3-5.2, and the IMO MODU Code 2009, the aforementioned product or design does not contain any form of asbestos.
- Dimensions and tolerances were verified as required by the design approval.
- · Material test reports (MTR) were reviewed and found to be the satisfaction of the attending Surveyor. Where required by the Rules, ABS

NOTE: This Report evidences that the survey reported herein was carried out in compliance with one or more of the Rules, guides, standards or other criteria of the American Bureau of Shipping and is issued solely for the use of the Bureau, its committees, its clients or other authorized entities. This Report is a representation only that the vessel, structure, item of material equipment, machinery or any other item covered by this Report has been examined for compliance with, or has met one or more of the Rules, guides, standards or other criteria of American Bureau of Shipping. The validity, applicability and interpretation of this Report is governed by the Rules and standards of American Bureau of Shipping who shall remain the sole judge thereof. Nothing contained in this Report or in any notation made in contemplation of this Report shall be deemed to relieve any designer, builder, owner, manufacturer, seller, supplier, repairer, operator or other entity of any warranty express or implied.



Work Order: First Visit Date: **Last Visit Date:** Vendor Purchase

26-Aug-2024 26-Aug-2024

6572776-B

127108/132725

Order Number:

Survey Location: Oslo

material certification reports have been verified.

- Plan review and/or Product Design Assessment (PDA) has identified design restrictions and/or limitations which are to be referenced upon installation onboard the vessel.
- Rule required testing (pressure/load/operational/proof-load/etc.) of the equipment/component was witnessed to the satisfaction of the attending Surveyor.
- Subject to satisfactory installation, testing and trials after installation onboard the vessel.
- Testing machines are maintained in a satisfactory condition and records of their recheck or calibration dates confirmed.

Statement/Observation

Set of Two (2) Valves intended for for Echo Sounder Transducer, Doppler Log Sensor, or Speed Log Sensor installation.

Valves assembly may include Intermediate Element, Bottom Flange, Blanking Plate, Intermediate tube, Intermediate Flange.

Hydrostatic pressure test was carried out at 5 bar with closed valve for 5 minutes in accordance with 2024 ABS Marine Vessel Rules 4.6.2/7.3.2.

No leakage or plastic deformation were noted during testing.

Material certificates of valves, intermediate elements and bottom flanges were provided by the Manufacturer and satisfactorily reviewed.

The valves were found covered by ABS Product Design Assessment no. 22-2329626-PDA.

Closing Paragraph:

The component/equipment was surveyed in accordance with the Rules, specifications, and approved drawings, as applicable, and is eligible for installation on board an ABS classed vessel subject to satisfactory installation and testing, as necessary.

Attending Surveyor(s):

Fuglei, Tor Brodde

Signed-off Date: 27-Aug-2024

Reviewing Surveyor(s)

Work Order Reviewer: Vocke, Sebastian Work Order Credit Date: 27-Aug-2024